

TABLE OF CONTENTS

1	Chapter 1 General Troubleshooting	49	Chapter 10 Blisters	109	Chapter 21 Discoloration
7	Chapter 2 Understanding the Molding Process	55	Chapter 11 Blush	115	Chapter 22 Flash
17	Chapter 3 Venting the Mold	61	Chapter 12 Bowling	121	Chapter 23 Flow Lines
21	Chapter 4 Understanding the Material	67	Chapter 13 Brittleness	127	Chapter 24 Gloss (low)
25	Chapter 5 The Operator	73	Chapter 14 Bubbles (voids)	133	Chapter 25 Jetting
27	Chapter 6 Recommended Melt Temperatures	79	Chapter 15 Burn Marks	139	Chapter 26 Knit Lines (Welds)
31	Chapter 7 Recommended Mold Temperatures	85	Chapter 16 Clear Spots	143	Chapter 27 NonFill (Short Shots)
33	Chapter 8 Glossary of Common Terms	89	Chapter 17 Cloudy Appearance	149	Chapter 28 Shrinkage (Excessive)
43	Chapter 9 Black Specks	95	Chapter 18 Contamination	155	Chapter 29 Sink Marks
		99	Chapter 19 Cracking/Crazing	161	Chapter 30 Splay
		103	Chapter 20 Delamination	167	Chapter 31 Warpage